


US POS SCANNER SETUP BARCODES

Scan 1st



*ensure to wait 8-10 seconds after scanning each barcode

Scan 2nd



*ensure to wait 8-10 seconds after scanning each barcode

Scan 3rd



*Scanner will power cycle after scanning, ensure to wait 8-10 seconds after scanning each barcode

Scan 4th



*ensure to wait 8-10 seconds after scanning each barcode

A) Re-initialize Scanner

- 1) Once the 4 barcodes have been scanned, on each POS, press the FUNCTION MENU button
- 2) Press the TOGGLE button until REFRESH DEVICES is visible
- 3) Press the REFRESH DEVICES button
- 4) Press the RE-INITIALIZE SCANNER button